

Access Road Stabilization - Route 92 West from Route 35 to Pilarcitos Creek

September 1992



Surface stabilization implemented by applying rice straw and sterile cereal grain followed by light incorporation into the soil surface.



Restored and stabilized road viewed from across the canyon.



Dozer shapes and compacts soil placed on the road prism, prior to placing erosion control materials.